


Serial Port Upgrade Instructions

1. Download the serial port driver (CP2102 USB Driver)



Select the appropriate driver version based on your PC system (simply click "Next" to proceed with installation).

[查看有关计算机的基本信息](#)



2. Download the downloader tool

After downloading, just unzip the package to use it directly.



Note:

Insert the serial port into the computer, and connect the other end (TYPE-C) to the headset. The upgrade will start automatically.

If there is no response, try pressing a few buttons on the headset.

If it keeps displaying "Scanning" without response, the issue may be that the host serial port is not sensitive. Try reinserting it or switching to a different USB port.